

VA - No A/E To Ground

Return to
Quinn

53-36

COSTS -- GET THEM -- KNOW THEM -- USE THEM

Get them

Henry Ford

Motor Dept.

Laundry Dept.

X-Ray

cost of sample part

Labor & Material only

Can't take costs out of plant

All blanked out

Know them

Labor

Material

Overhead

Shop

Out of pocket

Standard

Actual

Normal

Decision

Variance

Prime

Mfg.

"Bad rides with good"

NO more

Do costs support right decisions (general overhead rates

(engrg. liquidations

Use Them

Evaluate - each plant's practice may vary.

Make us make your sample

First time

Bellows

Cover cold control

2-1/2¢ more

Get them -- Know them -- Use them

Re-evaluate all of our thinking.

M/

August 1955, Lynn Med. Steam Turbine Value Analysis Seminar

COSTS -- GET THEM -- KNOW THEM -- USE THEM

Get them

Henry Ford
Motor Dept.
Laundry Dept.
X-Ray

Labor & Material only
Can't take costs out of plant
All blanked out

Know them

Labor
Material
Overhead
Shop
Out of pocket
Standard
Actual
Normal
Decision
Variance
Prime
Mfg.

"Bad rides with good"

NO more

Do costs support right decisions (general overhead rates
(enrg. liquidations

Use Them

Evaluate - each plant's practice may vary.

Bellows

First time

Cover cold control

2-1/2¢ more

Get them -- Know them -- Use them

Re-evaluate all of our thinking.

M/

August 1955, Lynn Med. Steam Turbine Value Analysis Seminar

Aug 1955
Japan

Costs - Get them - Know them - Use them

Get them

motor sept labor & matl only
sanding sept - cant take cost out of plot
x Roy - all blanked out

Know them

labor
matl
OH
shop
OP
Standard
out of
normal
Decision
variance
Prime

mpg

Use them

Evaluate - 3rd plant
Olson First time
Bellows - Cover cold control -
2 1/2 \$ more -

high id at
2 m



Use them to off a